

Catalog No. L51788e



## **Repair of Pipeline Dents Containing Minor Scratches**

**PR- PR 218-9508**

**Prepared for the  
Materials Committee**

**of  
Pipeline Research Council International, Inc.**

**Prepared by the following Research Agencies:**

**Kiefner & Associates, Inc.**

**Authors:  
J.F. Kiefner and C.R. Alexander**

**Publication Date:  
March 18, 1999**

## TABLE OF CONTENTS

	<i>Page</i>
<b>EXECUTIVE SUMMARY</b> .....	i
<b>INTRODUCTION</b> .....	1
<b>BACKGROUND</b> .....	2
<b>Historical Use of Grinding</b> .....	2
<b>Basis of the Work Described in this Report</b> .....	3
<b>DEVELOPMENT OF A TEST METHOD</b> .....	5
<b>Notch and Indentation Procedures</b> .....	6
<b>Pipe Materials</b> .....	8
Specimen Numbers .....	9
Preliminary Dent Tests .....	10
Preliminary Notch and Dent Tests .....	11
<b>BURST TESTING</b> .....	12
Group 1 .....	13
Group 2 .....	16
Group 3 .....	18
Group 4 .....	20
Group 5 .....	22
Group 6 .....	23
Group 7 .....	25
<b>Conclusions from the Burst Tests</b> .....	25
<b>FATIGUE TESTING</b> .....	26
<b>Development of the Fatigue Test Matrix</b> .....	27
Fatigue Testing Experimental Procedures .....	27
<b>Fatigue Test Results</b> .....	28
Group 1 (F2-3G, F2-4N, F2-5G, F2-6N) .....	29
Group 2 (F2-7G, F2-8N) .....	32
Group 3 (F2-9G, F2-10N, F2-11G, F2-12N, F3-13G, F3-14N) .....	32
Group 4 (F4-15G, F4-16N) .....	33
Group 5 .....	34
<b>Conclusion from the Fatigue Tests</b> .....	36
<b>ANCILLARY TESTS, MEASUREMENTS AND ANALYSES</b> .....	36
<b>Indenter Load Versus Indentation</b> .....	36
<b>Effects of Dent and Notch Parameter Variations</b> .....	37
Tests P1A, P1B, P1C, and P1D .....	38
Tests P2A, P2B, P2C, and P2D .....	40
Tests P3A, P3B, P3C .....	40
<b>Rerounding</b> .....	41
General .....	41
<b>Rerounded Shapes for the Various Indenters</b> .....	42

<b>Shakedown with Repeated Cycles of Pressurization</b> .....	42
<b>A Case of Actual Damage Which Caused a Pipeline to Fail in Service</b> .....	43
<b>GUIDELINES FOR REPAIR BY GRINDING</b> .....	45
<b>Pressure Reduction</b> .....	45
<b>Cleaning and Characterizing the Pipe and the Defect</b> .....	45
<b>Grinding and Inspecting</b> .....	46
<b>Dent Depth and Other Limitations</b> .....	48
<b>REFERENCES</b> .....	49

## TABLE OF CONTENTS (Continued)

### List of Tables

Table 1. Burst Tests .....	47
Table 2. Fatigue Tests .....	48
Table 3. Measurements of Dent Parameters .....	49
Table 4. Ancillary Tests .....	50
Table 5. Changes in Dent with Successive Cycles of Pressurization .....	51

### List of Figures

Figure 1. Axially-oriented 90° V-shaped notch prior to indentation .....	52
Figure 2. Schematic illustration of indentation mechanism .....	52
Figure 3. Types of indenters used in project .....	53
Figure 4. Typical axial profile of dent .....	54
Figure 5. Types of notches used in project .....	54
Figure 6. Dent installation .....	55
Figure 7. Specimens B2-15N and B2-14G, typical of appearances of unrepaired and repaired specimens after being tested to failure .....	56
Figure 8. Location of the leak and appearance of the rerounded dent in repaired Specimen B6-22G .....	57
Figure 9. Appearance of dent in Specimen B5-24G .....	58
Figure 10. Fracture surface of B8-36N showing to large “separations” .....	59
Figure 11. Metallographic sections through two of the separations showing how initial ductile tearing at the notch was interrupted by separations .....	60
Figure 12. Results of burst tests on unrepaired specimens .....	61
Figure 13. Results of burst tests on specimens repaired by grinding .....	62
Figure 14. Residual dents in repaired Specimens F2-3G and F2-5N after leaks had developed .....	63
Figure 15. Close-up views of cracks which leaked in repaired Specimens F2-3G and F2-5G .....	64
Figure 16. Fracture surfaces of leaks in repaired Specimens F2-3G and F2-5G .....	65
Figure 17. Fracture surfaces of leaks in unrepaired Specimens F2-4N and F2-6N .....	66
Figure 18. Fracture surfaces of leaks in repaired and unrepaired specimens indented with modified indenter .....	67
Figure 19. Residual dents in repaired Specimens F2-9G, F2-11G, and F3-13G after leaks had developed .....	68
Figure 20. Close-up views of leaks in repaired Specimens F2-9G and F2-11G .....	69
Figure 21. Fracture surfaces of failures of unrepaired Specimens F2-10N, F2-12N, and F3-14N .....	70
Figure 22. Dents in Specimens F4-15G and F4-16N after completion of pressure cycles .....	71
Figure 23. Fracture surfaces of Specimens F4-15G and F4-1N .....	

## TABLE OF CONTENTS (Continued)

showing location of leaks .....	72
Figure 24. Repaired Specimens F6-17G and F6-19G showing locations of the leaks and metallographic sections.....	73
Figure 25. Metallographic sections from Specimen F6-17G.....	74
Figure 26. Metallographic sections from Specimen F6-19G.....	75
Figure 27. Fracture surfaces at leaks in unrepaired Specimens F6-18N and F6-20N .....	76
Figure 28. Indenter load vs. indentation with constant internal pressure in the pipe .....	77
Figure 29. Repaired Specimen PID (B7-37G) after pressure test.....	78
Figure 30. Metallographic sections taken from pipe in area of notch after test .....	79
Figure 31. Sections across notches of Specimens P3A and P3B.....	80
Figure 32. Section across notch of Specimen P3C .....	81
Figure 33. Relationship between rerounded residual dent depths and initial (target) dent depths .....	82
Figure 34. Rerounded shapes for the various indenters.....	83
Figure 35. Overview of ruptured pipe .....	84
Figure 36. View along inside surface of ruptured pipe showing numerous dents.....	85
Figure 37. Fracture created by gouge and dent.....	86
Figure 38. Overview of the damage which caused the failure.....	87
Figure 39. Metallographic section across origin.....	88
Figure 40. Enlarged view of damaged microstructure and ductile tears (image reversed from that of Figure 39 by system optics) .....	89